

CRUSHER BRONZE

MINING WEAR PARTS (MWP), IS A **NATIONAL SUPPLIER** OF **HIGH-QUALITY** AFTERMARKET CRUSHER AND PUMP PARTS.

Spares on the ground can be planned ahead of time to save the hassle of finding that critical part last minute. We hold high levels of stock across all our aftermarket bronze range to supply spares or last minute critical parts promptly to keep customers operations running.

All of our aftermarket crusher bronze parts come completely warranted for peace of mind.

AFTERMARKET BRONZE

Crusher bronze parts are used in cones, jaws, and gyratory crushers. These critical parts can operate under extreme loads and are temperature sensitive, so precision and quality are key to their success. Our aftermarket bronze parts are cast using proprietary processes that result in gas pocket elimination and uniform grain structure with wear resistance benefits due to the lead, aluminium, and bronze combination.

QUALITY

Quality begins before the product is cast. With the use of our in-house 3D scanning technology, our engineers provide accurate tolerances and dimensions to ensure your aftermarket parts fit as expected and that the metallurgy is appropriately proportioned for each application.

The foundries we partner with use the latest machining and inspection processes before shipping items to ensure our aftermarket parts are within the set tolerances and will perform as expected. Parts then arrive at our facilities, where they undergo further quality control checks to confirm that these critical parts are ready for our

INNOVATION

customers.

Our team enjoys going above and beyond to enhance bronze internals further to provide aftermarket parts with increased wear resistance resulting in extended product life and improved performance. Get in touch today to discuss the shortcomings of your product, and we'll provide an innovative solution tailored to your needs, not ours.

- Upper head bush
- Lower head bush
- Eccentric bush
- Thrust bearing
- Socket Liner
- Thrust ring
- Swing Stock Bushes
- Countershaft bush
- Step washer



TIP: To maximise your bronze crusher parts, make sure they operte in clean oil and at the right temperature.